

2008s3591 RENEWABLE ENERGY PLANT BRIGG
Summary of Ground Water Levels from Boreholes in Contamination Report

BH No	Ground Level m AOD	First WL strike		Comment	Second WL strike		Rose to		Comment
		depth	m AOD		depth	m AOD	depth	m AOD	
1A	2.6	1.2	1.4	Seepage	3.0	-0.4	1.8	0.8	medium inflow
2	2.6	1.3	1.3	Seepage	3.3	-0.7	1.7	0.9	medium inflow
3	2.5				2.8	-0.3	1.9	0.6	medium inflow
4	3.1				3.2	-0.1	2.1	1.0	medium inflow
6	3.3				2.9	0.4	1.9	1.4	medium inflow
7	3.1				3.1	0.0	2.6	0.5	medium inflow
10	3.5				3.0	0.5	2.6	0.9	medium inflow
11	5.8				4.2	1.6	4.0	1.8	medium inflow
12A	4.3								Dry BH end 4.3 depth
13	3.3				3.0	0.3	2.5	0.8	medium inflow
14	2.9				2.9	0.0	2.4	0.5	medium inflow